

GENERAL MITCHELL INTERNATIONAL AIRPORT

Runway Safety Area Improvements Environmental Assessment







AIRPORT PROPERTY LINE

Figure 1 Existing Conditions

